



The Harbour Office
2nd Floor ABP Port Office
Old Quay Road
Teignmouth
TQ14 8ES
01626 773165
thc@teignmouthharbour.com

Issue Date: 02 October 2026

TEIGNMOUTH HARBOUR COMMISSION – LOCAL NOTICE TO MARINERS 09/26
INNER SPRATT ROCKS STBD HAND LIGHT EXTINGUISHED

Mariners are advised that INNER SPRATT STBD Hand Buoy FL G 2s is temporarily removed due to damage. BA Chart 26 Inset C refers. Any vessel approaching Teignmouth are to do so with caution.

A handwritten signature in black ink, appearing to read 'R M J Parsons', is written over a light blue rectangular background.

R M J Parsons
Harbour Master & CEO
Teignmouth Harbour Commission
ABP Millbay and Teignmouth