




The Harbour Office
2nd Floor ABP Port Offices
Old Quay Road
Teignmouth
TQ14 8ES
Tel:01626 773165
harbourmaster@teignmouthharbour.com

Issue Date: 30/09/2024

TEIGNMOUTH HARBOUR COMMISSION – LOCAL NOTICE TO MARINERS 12/24

NOTIFICATION OF Starboard Hand Channel Buoys Out Of Position/Missing

All vessels, please be advised that the Teignmouth Channel approaches Outer Starboard Hand buoy is missing and that the Outer Spratt Sands Starboard Hand Buoy is off station to the NNW of required position. Buoys can be identified from the PDF abstract of a UKHO Teignmouth Harbour chart below (not to be employed for navigation).



Mariners are reminded that AIS, CCTV, and VHF Channel 12 are recorded 24/7.

Captain Toby Dean
Harbour Master & CEO
Teignmouth Harbour Commission
Harbour Master ABP, Teignmouth and Millbay Plymouth
www.teignmouthharbour.com