




The Harbour Office
2nd Floor ABP Port Offices
Old Quay Road
Teignmouth
TQ14 8ES
Tel:01626 773165
harbourmaster@teignmouthharbour.com

Issue Date: 13/10/2024

TEIGNMOUTH HARBOUR COMMISSION – LOCAL NOTICE TO MARINERS 14/24

NOTIFICATION OF LNTM 12 is now cancelled and Starboard Hand Channel Buoy Missing

All vessels, please be advised that the Teignmouth Channel approaches Outer Starboard Hand buoy remains missing. The Outer Sprat Sands Starboard Hand buoy (FIG 2s) is now back in the charted position. Buoys can be identified from the PDF abstract of a UKHO Teignmouth Harbour chart below (not to be employed for navigation).



Mariners are reminded that AIS, CCTV, and VHF Channel 12 are recorded 24/7.

Captain Toby Dean
Harbour Master & CEO
Teignmouth Harbour Commission
Harbour Master ABP, Teignmouth and Millbay Plymouth
www.teignmouthharbour.com